





C5 CONCRETE WASHOUT
SCALE: N.T.S.




D4 TEMPORARY TREE PROTECTION FENCE
SCALE: N.T.S.



TYPICAL FENCE POST SUPPORT DETAIL




GATE/CORNER POST DETAIL




WARNING SIGN DETAIL

C2 CHAIN-LINK TREE PROTECTION FENCE
SCALE: N.T.S.



INSTALLATION DETAIL



BAG DETAIL


C3 STANDARD SILT BAG - INLET SEDIMENT CONTROL DEVICE
SCALE: N.T.S.

APRON LOCATION	"d6"	"1a"	"1b"	"1c"	RIPRAP CLASS	"d"	COMMENTS
BASIN 1	0.33	5.0'	4.0'	6	A	12"	


NOTE: FILTER FABRIC SHALL BE INSTALLED UNDER ALL RIPRAP ON THIS PROJECT

CLASS	MINIMUM	MIDRANGE	MAXIMUM
A	2	4	6
B	5	8	12
1	5	10	17
2	9	14	23


NOTE: FILTER FABRIC SHALL BE INSTALLED UNDER ALL RIPRAP ON THIS PROJECT



ISOMETRIC VIEW




PLAN




SECTION A-A

A3 RIP RAP APRON
SCALE: N.T.S.




SILT FENCE OUTLET

B2 TEMPORARY SILT FENCE STONE OUTLET
SCALE: N.T.S.




SILT FENCE

A2 TEMPORARY SILT FENCE
SCALE: N.T.S.



SECTION A-A

B5 TIRE WASH
SCALE: N.T.S.



TEMPORARY STOCKPILE AREA DETAIL

C4 TEMPORARY STOCKPILE AREA DETAIL
SCALE: N.T.S.

**LINK APARTMENTS CALYX II
GLEN LENNOX-BLOCK 4**

OWNER: GRUBB PROPERTIES

REGULATOR: TOWN OF CHAPEL HILL (919) 968-2743

ARCHITECT: BB+M ARCHITECTURE (704) 334-1716


CIVIL ENGINEER: BALLENTINE ASSOCIATES, P.A. (919) 929-0481

CONTRACTOR: SAMET CORPORATION (919) 703-0263

PLANNING DEPT: TOWN OF CHAPEL HILL (919) 968-2743

*NOISE COMPLAINTS CAN BE REPORTED BY CALLING THE FOLLOWING NUMBER: (919) 801-1605

B4 TEMPORARY CONSTRUCTION SIGN
SCALE: N.T.S.



TEMPORARY CONSTRUCTION ENTRANCE

A4 TEMPORARY CONSTRUCTION ENTRANCE
SCALE: N.T.S.

ENGINEERING DEPARTMENT

ENGINEERING DEPARTMENT

Maintenance:

- INSPECT SILT FENCE STONE OUTLET AT LEAST ONCE A WEEK AND AFTER EACH RAINFALL. MAKE ANY REQUIRED REPAIRS IMMEDIATELY. REMOVE SEDIMENT DEPOSITS AS NECESSARY. RESTORE TO ITS ORIGINAL DIMENSIONS AND REPLACE STONE THAT IS IMPAIRED BY SEDIMENT.

Maintenance:

- INSPECT SEDIMENT FENCES AT LEAST ONCE A WEEK AND AFTER EACH RAINFALL. MAKE ANY REQUIRED REPAIRS IMMEDIATELY. SHOULD THE FABRIC OF SEDIMENT FENCE COLLAPSE, TEAR, DECOMPOSE OR BECOME INEFFECTIVE, REPLACE IT PROMPTLY.
- REMOVE SEDIMENT DEPOSITS AS NECESSARY TO PROVIDE ADEQUATE STORAGE VOLUME FOR THE NEXT RAIN AND TO REDUCE PRESSURE ON THE FENCE. TAKE CARE TO AVOID UNDERMINING THE FENCE DURING CLEANOUT.
- REMOVE ALL FENCING MATERIALS AND UNSTABLE SEDIMENT DEPOSITS AND BRING THE AREA TO GRADE AND STABILIZE IT AFTER THE CONTRIBUTING DRAINAGE AREA HAS BEEN PROPERLY STABILIZED.

BALLENTINE ASSOCIATES, P.A.
221 PROVIDENCE ROAD, CHAPEL HILL, N.C. 27514
(919) 929-0481

DATE: 08 APR 22
08 APR 22
10 JUN 22
08 JUL 22

REVISIONS

DATE: 18 FEB 22
08 APR 22
10 JUN 22
08 JUL 22

ISSUED

DATE: 18 FEB 22
08 APR 22
10 JUN 22
08 JUL 22

OWNER INFORMATION

GRUBB PROPERTIES
117 EDENBURGH SOUTH DRIVE
SUITE 110
CARY, NC 27511
OWNERS REPRESENTATIVE:
JOE DYE
(919) 388-5774
FAX (919) 000-0000

LINK APARTMENTS CALYX II
GLEN LENNOX - BLOCK 4 - PHASE 1
CHAPEL HILL, NC

DACP DRAWINGS

JOB #: 107013.41
DATE: 18 FEB 22
SCALE: AS NOTED
DRAWN BY: D.W.S.
REVIEWED BY: G.J.R.

SHEET

C5301-1