

From: Axon, Amy [mailto:amy.axon@ncdenr.gov]
Sent: Thursday, July 13, 2017 4:13 PM
To: Steve Hart <SHart@harthickman.com>
Cc: Curtis Brooks <cbrooks@townofchapelhill.org>; Wendy Simmons <wsimmons@townofchapelhill.org>; Lance Norris <lnorris@townofchapelhill.org>; Qi, Qu <qu.qi@ncdenr.gov>
Subject: RE: Town of Chapel Hill Police Department

Steve:

Thank you for your response to my comments and providing a revised report. However, one of my comments was not completely addressed.

In comment #3 I asked that the text and the map (figure No. 7) be revised to indicate that erosional CCP was observed south of Bolin Creek Trail. I see that some text was revised, however the map was not revised and the first bulleted item under 4.2.1 states that "There were no observations of CCP in soil south of the Bolin Creek Trail". Please note that not only did DEQ staff and Curtis Brooks observe CCP in the areas discussed, but the soil samples collected below the greenway (SS-4, SS-5, SS-6 and SS-7) detected elevated levels of arsenic, cobalt and manganese. Which are constituents we have been seeing in the CCP at the site.

Please revise the map to indicate the approximate area of CCP Depositional layer south of the Bolin Creek Trail and make necessary revisions to all text that refer to observations of CCP south of the Bolin Creek Trail.

I understand that you may have questions about what I am asking for. I am more than happy to discuss via a phone call if it would help to clarify and expedite a resolution to this issue.

I would also like to talk with you to discuss plans for responding to the SELC's most recent comments, submitted on May 9, 2017. Therefore, please contact me at your earliest convenience.

Thanks
Amy

Amy Axon
Hydrogeologist
DWM, Superfund Section
Department of Environmental Quality

919 707 8371 office
amy.axon@ncdenr.gov

217 West Jones Street
1646 Mail Service Center
Raleigh, NC 27699



 Nothing Compares 