

S. WEST COR. ROSEMARY & HENDERSON ST
 R/W AND WALL PROBLEM - NO 4' LANDING AT TOP
 NO 4'x4' LEVEL CLEAR SPACE OUTSIDE
 VEHICLE TRAVEL PATH

